CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000772A

DATE: 18-Dec-13

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	MAX9171ETA	MAX9172ETA+	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171ETA+	MAX9172EKA+	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171ETA+T	MAX9172ETA+T	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171ETA-T	MAX9172ETA+T	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171EKA	MAX9172EKA+	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171EKA+	MAX9172EKA+	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171EKA+T	MAX9172EKA+T	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171ESA+	MAX9172ESA+	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171ESA+T	MAX9172ESA+T	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured
Discontinuance	MAX9171ESA-T	MAX9172ESA+T	18-Dec-2013	18-Dec-2015	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 1/19/2013