



CUSTOMER OPERATIONS  
160 RIO ROBLES  
SAN JOSE, CA 95134

PDN #: M001082I

DATE: 14-Sep-2022

## PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1806E-010+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	DS28E15X+U	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	DS34T101GN+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	ICM7212AMIQH+D	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	ICM7212AMIQH+TD	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX110BCAP+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX1142AEAP+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX128BENG+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX1294AEEI+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX1793EUE33/V+CM1	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX2370ETM+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX2370ETM+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX292CWE+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX31840EVKIT#	N/A	26-Sep-2022	27-Mar-2024	EVKIT is No Longer Supported
Discontinuance	MAX4668CPE+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX505ACNG+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX5153AEEE+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX5153AEEE+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX521AEWG+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX521AEWG+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX5251BCPP+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX6328XR28+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX6328XR28+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX6389XS33D1+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX6389XS33D1+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX6389XS33D2+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 15-Oct-2022

Discontinuance	MAX6389XS33D2+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX6701MKA+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX6701MKA+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX709TCPA+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX908EPD+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX9117ESA+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX9117ESA+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX98931EWX+	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured
Discontinuance	MAX98931EWX+T	N/A	26-Sep-2022	27-Mar-2024	Part can no longer be manufactured