


## Product Change Notification - SYST-28LNPV064

<b>Date:</b>	29 Mar 2017
<b>Product Category:</b>	Driver / Interface ICs
<b>Affected CPNs:</b>	
<b>Notification subject:</b>	Data Sheet - HV508 High-Voltage Liquid Crystal Shutter Driver Data Sheet
<b>Notification text:</b>	SYST-28LNPV064

Microchip has released a new DeviceDoc for the HV508 High-Voltage Liquid Crystal Shutter Driver Data Sheet of devices. If you are using one of these devices please read the document located at [HV508 High-Voltage Liquid Crystal Shutter Driver Data Sheet](#).

**Notification Status:** Final

**Description of Change:** 1) Converted Supertex Doc# DSFP-HV508 to Microchip DS20005728A 2)Removed "HVC MOS® Technology" throughout the data sheet 3)Changed part marking format 4)Changed the quantity of the 8-lead SOIC LG package from 2500/Reel to 3300/Reel 5)Made minor text changes throughout the document

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Manufacturability

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 29 March 2017

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

**Attachment(s):** [HV508 High-Voltage Liquid Crystal Shutter Driver Data Sheet](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

### Terms and Conditions:

If you wish to change your product/process change notification (PCN) profile please log on to our website at <http://www.microchip.com/PCN> sign into myMICROCHIP to open the myMICROCHIP home page, then select a profile option from the left navigation bar.

To opt out of future offer or information emails (other than product change notification emails), click here to go to [microchipDIRECT](#) and login, then click on the "My account" link, click on "Update profile" and un-check the box that states "Future offers or information about Microchip's products or services."

Affected Catalog Part Numbers (CPN)

HV508LG-G