

PDN Number:	20160811000	PDN Date:	Nov. 2, 2016
Title:	Discontinuance of Select Devices Sourced in GFAB		
Customer Contact:	PCN Manager	Dept:	Quality Services
Last date to order:	Nov. 2, 2017	Last date to ship:	May 2, 2018
Change Type:	Product Discontinuance - End Of Life		
Product Discontinuance Notification Details			
Description of Withdrawal/Discontinuance:			
Texas Instruments, Incorporated (TI) is announcing the discontinuance of select devices sourced in GFAB. A lifetime buy is being offered with the date given above. Recommended replacements are being offered on most devices as shown in page 2 of this document.			
NOTE: There are no samples offered for withdrawn/obsolete products. If you have any questions, please contact your local sales representative.			
Reason for Withdrawal/Discontinuance:			
GFAB site closure			
Product Affected:			
Please see affected device list on page 2.			

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com

20160811000
Attachments1

Products Affected:

The devices listed on this page may be a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

For this PDN, in addition to listing the TI Affected Device and the Customer Part # (if available) in the table below, we are also including a suggested Replacement Device (two options if available) and the Replacement Code (two options if available). If there is a second Replacement Device/Code option available, there will be a new entry on a separate row:

Affected Device	Replacement	Code	Customer Part# (if available)
-----------------	-------------	------	-------------------------------

Replacement Code Key:

- F = Similar functionality but not equivalent.
- P = Same functionality but not pin-for-pin equivalent and may not be parametrically equivalent.
- Q = Same functionality and PIN-OUT as the compared device but is NOT an exact equivalent.
- S = EXACT equivalent in functionality and parametrically to the compared device.
- NA = Not Applicable

AFFECTED DEVICE	REPLACEMENT	CODE	CUSTOMER PART NUMBER
DS14185WM	None	Not Applicable	null
DS14185WM/NOPB	None	Not Applicable	null
DS14185WMX/NOPB	None	Not Applicable	null
DS36C280M/NOPB	None	Not Applicable	null
DS36C280TM/NOPB	None	Not Applicable	null
LM2657MTC/NOPB	LM2647MTC/NOPB	Q	null
LM2726M/NOPB	LM27222MX/NOPB	Q	null
LM2825HN-ADJ/NOPB	LMZ14201H	F	null
LM2825N-3.3/NOPB	LMZ14201	F	null
LM2825N-5.0/NOPB	LMZ14201	F	null
LM2825N-ADJ/NOPB	LMZ14201H	F	null
LM3490IM5-12/NOPB	None	Not Applicable	null
LM3490IM5-3.3/NOPB	LP2951ACMM-3.3/NOPB	P	null
LM3490IM5-5.0/NOPB	LP2951ACMM/NOPB	P	null
LM3490IM5X-12/NOPB	None	Not Applicable	null
LM3557SD-2/NOPB	TPS61161ADRVR	P	null
LM3557SD-2/NOPB	TPS61161DRVR	P	null
LM4562HA/NOPB	LM4562MAX/NOPB	F	null
LM4562HA/NOPB	OPA1602AIDR	F	null
LM4804LQ/NOPB	TPA2015D1YZHR	F	null
LM4804LQ/NOPB	TPA2080D1YZGR	F	null
LM5035AMH-1/NOPB	LM5035BMH/NOPB	P	null
LM5035AMH/NOPB	LM5035BMH/NOPB	Q	null
LM5035ASQ/NOPB	LM5035BSQ/NOPB	Q	null
LM96530SQE/NOPB	None	Not Applicable	null
LMC568CM/NOPB	LMC568CMX/NOPB	F	null
LME49713HA/NOPB	THS3121CD	F	null
LME49720HA/NOPB	LME49720MAX/NOPB	F	null
LME49720HA/NOPB	OPA1602AID	F	null
LPC661IM/NOPB	LMC6061IM/NOPB	Q	null
LPC661IMX/NOPB	LMC6061IMX/NOPB	Q	null

LM2726M	LM27222MX/NOPB	Q	null
LM2744MTC/NOPB	LM27403SQE/NOPB	P	null
LM2825N-12/NOPB	LMZ14201H	F	null
SM72238TD-3.0/NOPB	LP2950CDT-3.0/NOPB	S	null

Technical details of this Product Change follow on the next page(s).