

# INFORMATION NOTE



N° 024/16

## Reduced pocket size in the carrier tape of package PG-ATSLP-12

**Subject of Change:** Carrier tape pocket size decreased


Products affected:	Type	SP N°	OPN	Package
	BGM 15LA12	SP001215968	BGM15LA12E6327XTSA1	PG-ATSLP-12
	BGM 15MA12	SP001215972	BGM15MA12E6327XTSA1	PG-ATSLP-12
	BGM 15HA12	SP001215980	BGM15HA12E6327XTSA1	PG-ATSLP-12
	BGS 15MA12	SP001219716	BGS15MA12E6327XTSA1	PG-ATSLP-12
	BGS 15M2A12	SP001273574	BGS15M2A12E6327XTSA1	PG-ATSLP-12

**Reason of Change:** Quality improvement

### Description of Change:


#### Old

Ao (pocket X-axis) : 1.4 mm  
Bo (pocket Y-axis) : 2.15mm



#### New

Ao (pocket X-axis) : 1.3 mm  
Bo (pocket Y-axis) : 2.1 mm



**Assessment:** No change of Form, Fit & Function of the products. Carrier tape change only.

**Time Schedule:** Production change start from Date-code 1614 onwards.  
\*note during transition period (4weeks), there will be mix of the old and new carrier tape for older date code.

Estimate start of delivery: 2<sup>nd</sup> May 2016 onwards

**Documentation:** Not applicable

If you have any questions, please do not hesitate to contact your local Sales office.