INFORMATION NOTE



N° 047/15

Implementation of a far dambar leadframe design for PG-DSO-28-22 as second source

Subject of Change: Implementation of a far dambar leadframe design for PG-DSO-28-22 as

second source

Products affected: Type SP N° OPN **Package** BTM7700G SP000306876 BTM7700GXUMA1 PG-DSO-28-22 BTM7740G PG-DSO-28-22 SP000306879 BTM7740GXUMA1 BTM7741G SP000306880 BTM7741GXUMA1 PG-DSO-28-22

BTM7750G SP000306881 BTM7750GXUMA1 PG-DSO-28-22 BTM7751G SP000306882 BTM7751GXUMA1 PG-DSO-28-22

Reason of Change: Implementation of second source supplier

Description of Change:

Old close dambar



New (additional) far dambar



Assessment: No impact on electrical parameters.

No impact for pick and place at board assembly expected.

Time Schedule: Anticipated implementation of change: 2015-08-01

If you have any questions, please do not hesitate to contact your local Sales office.

2015-07-07 Page 1 of 1