

Microsemi Corporation

July 28, 2014

PDN 149982: Product Discontinuance Notice – Products single-sourced in IBM SiGe 5hp process

Description of Change:

Microsemi is announcing the discontinuance of the products listed in Appendix A, due to IBM's EoL notification to Microsemi which stated EoL buys for products built using SiGe 5hp foundry technology.

Reason for Discontinuance:

The decision to discontinue these products was made by IBM.

Customer Impact:

These devices are being removed from Microsemi's product offering. These products will no longer be available for order after April 30, 2015. There is a limited inventory of these parts, so orders will be taken on a first-come, first-served basis. Please contact your local Microsemi Sales Office for information regarding conversion to alternate parts.

Product may be limited in availability. Orders will be supported on a first-come-firstserve basis. Orders for these products will be non-cancelable and non-returnable.

Last Order Date: April 30, 2015

Please note that all orders must be booked as non-cancelable non-returnable (NCNR) by no later than April 30, 2015. No new orders will be accepted after this date. Although Microsemi will attempt to accommodate all requirements, it is highly recommended that orders be placed as far as possible in advance of the order deadline. The inventory is limited so orders will be taken on a first-come, first-served basis.



Last Shipment Date: April 30, 2016

Please note that Microsemi will continue to ship last-time-buy orders as requested only through April 30, 2016. Product orders must be scheduled to ship no later than this date.

Products Affected by this Discontinuance:

See Appendix A.

Contact Information:

Communications and Medical Products Group cmpg.quality@microsemi.com

Regards,

Discontinuance Notice

Microsemi Corporation

Any projected dates in this notification are based on the most current product information at the time this PDN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Microsemi Sales Office, the factory contact shown above, or your local distributor.

This PDN is confidential and proprietary information of Microsemi and is intended only for distribution by Microsemi to its customers, for customers' use only. It must not be copied or provided to any third party without Microsemi's prior written consent.



Appendix A:

List of products affected.

For these devices, there are no pin compatible replacement devices.

| Ordering Part Number | Device Similar in Function |
|----------------------|-------------------------------|
| ZL30406QGG1 | ZL30158GGG2 |
| ZL30414QGG1 | ZL30158GGG2 |
| ZL30415GGG2 | ZL30151LDG1 |
| ZL30415GGF2 | ZL30151LDG1 |
| ZL30416GGG2 | ZL30151LDG1 |
| ZL30417QGG1 | ZL30158GGG2 |

Microsemi Corporation One Enterprise, Aliso Viejo CA 92656 USA Within the USA: +1 (949) 380-6100 · Sales: +1 (949) 380-6136 Fax: +1 (949) 215-4996 · <u>www.microsemi.com</u>