



Product Change Notification

TE Connectivity

Product Change Notification: E-17-013712

PCN Date: 10-OCT-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Univer Mate-N-Lok plug Housing

Description of Changes
Material upgrade for better supply chain.

Reason for Changes:
Product Improvement. Material upgrade for better supply chain.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	15-JAN-2018
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	15-FEB-2019

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350777-2	NO						
1-350777-6	NO						
1-350777-9	NO						
350715-1	NO		350715-1-ND	'402723738", "AMP-0-0350715-1", "E04329-000"			
350715-4	NO			'C46515-000", "AMPS-0-0350715-4"			
350720-1	NO			'403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
350720-4	NO						
350735-4	NO						
350736-1	NO			'403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			'AMP-0-0350766-1", "F98408-000", "2-42939-5671"			
350766-4	NO						
350777-1	NO			'403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			'403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350779-4	NO						
350809-1	NO			'AMP-0-0350809-1", "E81588-000"			
350865-1	NO			'CU3087-000", "AMPS-0-0350865-1"			
350866-1	NO			'CU3088-000", "AMPS0-0350866-1"			
640581-1	NO			'405000886"			
640582-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-------------	---------------------------	------------------	----------------------	----------------------	------------------------	---------------------------------	---------------------------

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350777-2	NO						
1-350777-9	NO						
350715-1	NO		350715-1-ND	"402723738", "AMP-0-0350715-1", "E04329-000"			
350715-4	NO			"C46515-000", "AMPS-0-0350715-4"			
350720-1	NO			"403049182", "AMPS-0-0350720-1", "D76178-000", "500-020-2570"			
350735-4	NO						
350736-1	NO			"403431885", "AMPS-0-0350736-1", "D26199-000"			
350766-1	NO			"AMP-0-0350766-1", "F98408-000", "2-42939-5674"			
350766-4	NO						
350777-1	NO			"403311533", "AMPS-0-0350777-1", "C55004-000"			
350779-1	NO			"403426000", "AMP-0-0350779-1", "E78305-000", "651-1084-01"			
350779-4	NO						
350809-1	NO			"AMP-0-0350809-1", "E81588-000"			
350865-1	NO			"CU3087-000", "AMPS-0-0350865-1"			
350866-1	NO			"CU3088-000", "AMPS0-0350866-1"			
640581-1	NO			"405000886"			
640582-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350777-2	NO						
1-350777-6	NO						
1-350777-9	NO						
350720-4	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350777-6	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-350777-2	NO						
1-350777-6	NO						
1-350777-9	NO						
350720-4	NO						