

Product Change Notice

Issue Date: 18 Feb 2014

Change Type:

Introduction of replacement die source for Chiplid part numbers listed below:

Parts Affected:

List of part number:

HSMF-C113	HSMR-C150	QSMN-C124	QSMW-B123
HSMF-C115	HSMR-C170	QSMN-C185	QSMW-B193
HSMF-C114	HSMR-C190	QSMN-C186	QSMW-C12C
HSMF-C118	HSMR-C191	QSMN-C194	QSMW-C12E
HSMF-C164	HSMR-C197	QSMN-C199	QSMW-C12G
HSMF-C169	HSMR-C265	QSMR-C12D	QSMW-C19M
HSMN-C110	HSMW-B191	QSMR-C13Z	QSMW-C19N
HSMN-C120	HSMW-C120	QSMR-C153	QSMW-C13B
HSMN-C150	HSMW-C130	QSMR-C19B	
HSMN-C170	HSMW-C191	QSMR-C19J	
HSMN-C190	HSMW-C265	QSMR-C19N	
HSMN-C191	QSMF-C11H	QSMR-C19Q	
HSMR-C110	QSMF-C11K	QSMR-C262	
HSMR-C120	QSMF-C120	QSMR-C264	
HSMR-C130	QSMF-C11Q	QSMW-B121	

Description and Extent of Changes:

The selected die source (InGaN blue) met Avago qualification requirement.

Reasons for Change:

To ensure assurance of supply

Effect of Change on Fit, Form, Function, Quality, or Reliability:

There is no change on fit, form and function as per datasheet.

Effective Date of Change:

Shipment may contain both die sources starting 18 May 2014. No sorting is required.

Qualification Data:

Qualification data will be made available upon request.

These changes have been reviewed and approved by Avago Technologies engineers and managers per Avago Technologies procedure: Change Control and Customer Notification, A-5962-6052-80.

Please contact your Avago Technologies field sales engineer or Contact Center (<http://www.avagotech.com/contact/>) for any questions or support requirements.