

# **TE Connectivity**

## Product Change Notification: P-22-022958

## PCN Date: 27-JUN-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:	
0.5FH BTB Connectors	

#### Description of Changes

Following Part Numbers will be transferred from current TE Connectivity AMP Qingdao manufacturing location, CHINA to new manufacturing location---TE AMP Qingdao Ltd. High-tech Zone Branch, is 11KM from TE current Campus, which was located in Graphene Industrial Park in Qingdao

### Reason for Changes:

With the business growth, Assembly space is a constraint TE AMP Campus. Need to look for new assembly manufacturing location. Keep the stamping, molding and plating in exist TE AMP Campus. These process are no Change The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a TE quality management system control

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	27-SEP-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

#### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>3-1827233-6</u>	NO			"1377801"			
<u>3-1939755-6</u>	NO						
<u>3-1939756-6</u>	NO						
<u>3-5353652-6</u>	NO						
3-5353652-9	NO						

#### Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>3-</u> 1939755-6	NO						

#### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>3-</u> 1939755-6	NO						
<u>3-</u> 5353652-6	NO						
<u>3-</u> 5353652-9	NO						

# Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>3-</u> 1939755-6	NO						
<u>3-</u> 5353652-6	NO						

# Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>3-</u> 5353652-6	NO						

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>3-</u> 1827233-6	NO			"1377801"			
<u>3-</u> 1939755-6	NO						
<u>3-</u> 1939756-6	NO						
<u>3-</u> 5353652-6	NO						

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>3-</u> 1939755-6	NO						