

<b>PCN Number:</b>	20170615000	<b>PCN Date:</b>	June 27, 2017
<b>Title:</b>	Datasheet for LMR23625-Q1		
<b>Customer Contact:</b>	<a href="#">PCN Manager</a>	<b>Dept:</b>	Quality Services
<b>Change Type:</b>			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
		<input type="checkbox"/>	Wafer Bump Site
		<input type="checkbox"/>	Wafer Bump Material
		<input type="checkbox"/>	Wafer Bump Process
		<input type="checkbox"/>	Wafer Fab Site
		<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Wafer Fab Process

### Notification Details

**Description of Change:**

Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.



**LMR23625-Q1**

SNVSAR5A – DECEMBER 2016 – REVISED APRIL 2017

**Changes from Original (December 2016) to Revision A**

**Page**

• Changed this efficiency graph .....	1
• Changed the value of HBM to ±2000 from ±2500 .....	4
• Changed this efficiency graph .....	9
• Changed this efficiency graph .....	9
• Changed this efficiency graph .....	9
• Changed this efficiency graph .....	9

The datasheet number will be changing.

<b>Device Family</b>	<b>Change From:</b>	<b>Change To:</b>
LMR23625-Q1	SNVSAR5	SNVSAR5A

These changes may be reviewed at the datasheet links provided.

<http://www.ti.com/product/LMR23625-Q1>

**Reason for Change:**

To accurately reflect device characteristics.

**Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):**

No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.

**Changes to product identification resulting from this PCN:**

None.

**Product Affected:**

LMR23625CFQDDAQ1	LMR23625CFQDDARQ1	LMR23625CQDDAQ1	LMR23625CQDDARQ1
------------------	-------------------	-----------------	------------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

<b>Location</b>	<b>E-Mail</b>
USA	<a href="mailto:PCNAmericasContact@list.ti.com">PCNAmericasContact@list.ti.com</a>
Europe	<a href="mailto:PCNEuropeContact@list.ti.com">PCNEuropeContact@list.ti.com</a>
Asia Pacific	<a href="mailto:PCNAsiaContact@list.ti.com">PCNAsiaContact@list.ti.com</a>
Japan	<a href="mailto:PCNJapanContact@list.ti.com">PCNJapanContact@list.ti.com</a>