

Product Obsolescence Notification

Issue Date: 31-January-2023

Dear Customer:

Broadcom regrets to announce the obsolescence of the following products:

Broadcom Part Numbers	Description	Suggested Replacement
5082-7611-DE000	S4,0.3in,HER,CA,T/S Red	5082-7611-GH000
5082-7651-DE000	S4,0.43in,HER,CA,T/S Red	5082-7651-GH000
5082-7653-DE000	S4,0.43in,HER,CC,T/S Red	5082-7653-GH000
ASLC-6135D090H0	L4,Canopy Light,DWhite	NA
ASMF-PWG7-NNQHM	1W 3030 White LED	ASMF-PWG8-NPRHM
ASMT-AB31-NNP00	MS AV,3W Blue	ASM6-SBD3-NGJ0H
ASMT-AL00-NQS00	MS AV,1W RoBlue	NA
ASMT-AL31-NRS00	MS AV,3W RoBlue	ASM6-SLD2-NTV0H
ASMT-AN31-NWX00	MS AV,3W NWhite	ASM6-SWD1-NQTHH
ASMT-AN31-NWX01	MS AV,3W NWhite	ASM6-SWD1-NQTHH
ASMT-AW00-NUW00	MS AV,1W CWhite	ASMF-PWG8-NPRDM
ASMT-AW00-NUW01	MS AV,1W CWhite	ASMF-PWG8-NPRDM
ASMT-AW31-NVX00	MS AV,3W CWhite	ASM6-SWD1-NQTHH
ASMT-AW31-NVX01	MS AV,3W CWhite	ASM6-SWD1-NQTHH
ASMT-AW31-NVXL1	MS AV,3W CWhite	ASM6-SWD1-NQTHH
ASMT-AW31-NWXN1	MS AV,3W CWhite	ASM6-SWD1-NQTHH
ASMT-AY00-NUV01	MS AV,1W WWhite	ASMF-PWG8-NPRDM
ASMT-AY00-NVW00	MS AV,1W WWhite	ASMF-PWG8-NPRDM
ASMT-AY31-NUW00	MS AV,3W WWhite	ASM6-SWD1-NQTHH

Broadcom Part Numbers	Description	Suggested Replacement
ASMT-JL11-NQS01	MS JD,1W RBlue	NA
ASMT-JL31-NRS01	MS JD,3W RBlue	ASM6-SLD2-NTV0H
ASMT-JN11-NWX01	MS JD,1W NWhite	ASMT-JN32-NWY01
ASMT-JN33-NVW01	MS JD,3W Mini NWhite	ASMT-JN32-NWY01
ASMT-JW11-NWX01	MS JD,1W CWhite	ASMF-PWG8-NPRDM
ASMT-JW32-NWXH1	MS JD,3W Mini CWhite	ASMT-JW32-NWY01
ASMT-JW32-NWYJ1	MS JD,3W Mini CWhite	ASMT-JW32-NWY01
ASMT-JW33-NVW01	MS JD,3W Mini CWhite	ASMT-JW32-NWY01
ASMT-JY32-NWXK1	MS JD,3W Mini WWhite	ASMT-JY32-NWY01
ASMT-JY32-NWYK1	MS JD,3W Mini WWhite	ASMT-JY32-NWY01
ASMT-JY33-NTU01	MS JD,3W Mini WWhite	ASMT-JY32-NWY01
ASMT-MW05-NMMS0	MS,1W,Cool White	ASMT-MW05-NMNS1
ASMT-MW06-NMNS0	MS,1W,Cool White	ASMT-MW06-NMN01
ASMT-MW06-NMNW0	MS,1W,Cool White	ASMT-MW06-NMN01
ASMT-MW62-NGJ00	MS Clear,0.5W,Cool White	NA
ASMT-MW62-NGJ01	MS Clear,0.5W,Cool White	NA
ASMT-MW62-NGJR1	MS Clear,0.5W,Cool White	NA
ASMT-MW62-NGJW0	MS Clear,0.5W,Cool White	NA
ASMT-MW62-NHK00	MS Clear,0.5W,Cool White	NA
ASMT-MW62-NHK01	MS Clear,0.5W,Cool White	NA
ASMT-MY62-NGJ00	MS Clear,0.5W,Warm White	NA
ASMT-MY62-NHK00	MS Clear,0.5W,Warm White	NA
ASMT-MYE2-NMP00	MS Diff,3W,Warm White	NA
HDSP-3901-EF000	S4,0.8in,HER,CA	HDSP-3901-FG000
HDSP-3903-EF000	S4,0.8in,HER,CC	HDSP-3903-FG000
HDSP-4603-IJ000	S4,0.43in,Grn,CC	HDSP-4603-KL000
HDSP-4830-GH000	L-Bar,Array,1inL X .4inW,HER	HDSP-4830-JK000
HDSP-4830-HH000	L-Bar,Array,1inL X .4inW,HER	HDSP-4830-JJ000

Broadcom Part Numbers	Description	Suggested Replacement
HDSP-4850-HI000	L-Bar,Array,1inL X .4inW,Grn	HDSP-4850-JK000
HDSP-4850-HIC00	L-Bar, Array 1inL X .4inW,Grn	HDSP-4850-JKC00
HDSP-5501-GG000	S4,0.56S,HER,CA	HDSP-5501-JJ000
HDSP-5501-GH000	S4,0.56S,HER,CA	HDSP-5501-IJ000
HDSP-5503-GG000	S4,0.56S,HER,CC	HDSP-5503-JJ000
HDSP-5503-GH000	S4,0.56S,HER,CC	HDSP-5503-IJ000
HDSP-5507	S4,0.56S,HER,Overflow,CA	NA
HDSP-5507-GG000	S4,0.56S,HER,Overflow,CA	NA
HDSP-5507-GH000	S4,0.56S,HER,Overflow,CA	NA
HDSP-5508	S4,0.56S,HER,Overflow,CC	NA
HDSP-5508-GH000	S4,0.56S,HER,Overflow,CC	NA
HDSP-5521-GG000	S4,0.56D,HER,CA	HDSP-5521-JJ000
HDSP-5521-GH000	S4,0.56D,HER,CA	HDSP-5521-JK000
HDSP-5523-GH000	S4,0.56D,HER,CC	HDSP-5523-JK000
HDSP-5553-BC000	S4,0.56S,HER LC,CC	HDSP-5553-FG000
HDSP-5558	S4,0.56S,HER LC,Overflow CC	NA
HDSP-5601-GH000	S4,0.56S,Grn,CA	HDSP-5601-IJ000
HDSP-5603-GH000	S4,0.56S,Grn,CC	HDSP-5603-IJ000
HDSP-5607	S4,0.56S,Grn,Overflow,CA	NA
HDSP-5607-GH000	S4,0.56S,Grn,Overflow CA	NA
HDSP-5608	S4,0.56S,Grn,Overflow,CC	NA
HDSP-5621-GH000	S4,0.56D,Grn,CA	HDSP-5621-IJ000
HDSP-5621-GH400	S4,0.56D,Grn,CA	HDSP-5621-IJ400
HDSP-5623-GH000	S4,0.56D,Grn,CC	HDSP-5623-IJ000
HDSP-7501-CD000	S4,0.3M,HER,CA	HDSP-7501-GH000
HDSP-7501-CDZ00	S4,0.3M,HER,CA	HDSP-7501-GHZ00
HDSP-7503-CD000	S4,0.3M,HER,CC	HDSP-7503-GH000
HDSP-7503-DD000	S4,0.3M,HER,CC	HDSP-7503-HH000

Broadcom Part Numbers	Description	Suggested Replacement
HDSP-7511-CD000	S4,0.3M,HER LC,CA	HDSP-7511-HI000
HDSP-7513-CD000	S4,0.3M,HER LC,CC	HDSP-7513-HI000
HDSP-7801-JK000	S4,0.3M,Grn,CA	HDSP-7801-LM000
HDSP-7801-KK000	S4,0.3M,Grn,CA	HDSP-7801-MM000
HDSP-7803-JK000	S4,0.3M,Grn,CC	HDSP-7803-LM000
HDSP-7803-JKC00	S4,0.3M,Grn,CC	HDSP-7803-LMC00
HDSP-8601-EF000	S4,0.8in,Grn,CA	HDSP-8601-GH000
HDSP-8603-EF000	S4,0.8in,Grn,CC	HDSP-8603-GH000
HDSP-A213-CD000	S4,0.3M,HER,CC,T/S Black	HDSP-A213-GH000
HDSP-A511-JK000	S4,0.3M,Grn,CA,T/S Black	HDSP-A511-LM000
HDSP-F201-DE000	S4,0.4S,HER,CA	HDSP-F201-HI000
HDSP-F203-DE000	S4,0.4S,HER,CC	HDSP-F203-HI000
HDSP-F211-DE000	S4,0.4S,HER,CA,T/S Black	HDSP-F211-HI000
HDSP-F213-DE000	S4,0.4S,HER,CC,T/S Black	HDSP-F213-HI000
HDSP-F213-EF000	S4,0.4S,HER,CC,T/S Black	HDSP-F213-HI000
HDSP-F501-JK000	S4,0.4S,Grn,CA	HDSP-F501-LM000
HDSP-F503-JK000	S4,0.4S,Grn,CC	HDSP-F503-LM000
HDSP-F503-JK016	S4,0.4S,Grn,CC	HDSP-F503-LM016
HDSP-F511-IJ000	S4,0.4S,Grn,CA,T/S Black	HDSP-F511-LM000
HDSP-F511-IJC00	S4,0.4S,Grn,CA,T/S Black	HDSP-F511-LMC00
HDSP-F513-IJ000	S4,0.4S,Grn,CC,T/S Black	HDSP-F513-LM000
HDSP-H107	S4,0.56S,AllnGaP DR,Overflow,CA	NA
HDSP-H108	S4,0.56S,AllnGaP DR,Overflow,CC	NA
HDSP-H211-GH000	S4,0.56S,HER,CA,T/S Black	HDSP-H211-IJ000
HDSP-H213-GH000	S4,0.56S,HER,CC,T/S Black	HDSP-H213-IJ000
HDSP-H511-GH000	S4,0.56S,Grn,CA,T/S Black	HDSP-H511-IJ000
HDSP-H513-GH000	S4,0.56S,Grn,CC,T/S Black	HDSP-H513-IJ000
HDSP-K211-GH000	S4,0.56D,HER,CA,T/S Black	HDSP-K211-IJ000

Broadcom Part Numbers	Description	Suggested Replacement
HDSP-K213-GH000	S4,0.56D,HER,CC,T/S Black	HDSP-K213-IJ000
HDSP-K511-GH000	S4,0.56D,Grn,CA,T/S Black	HDSP-K511-IJ000
HDSP-K513-GH000	S4,0.56D,Grn,CC,T/S Black	HDSP-K513-IJ000
HDSP-U203-CD000	S4,0.3UM,HER,CC	HDSP-U203-HI000
HDSP-U211-CD000	S4,0.3UM,HER,CA,T/S Black	HDSP-U211-GH000
HDSP-U213-CD000	S4,0.3UM,HER,CC,T/S Black	HDSP-U213-GH000
HDSP-U501-J0C00	S4,0.3UM,Grn,CA	HDSP-U501-L0C00
HDSP-U501-KL000	S4,0.3UM,Grn,CA	HDSP-U501-MN000
HDSP-U503-KL000	S4,0.3UM,Grn,CC	HDSP-U503-MN000
HDSP-U511-KL000	S4,0.3UM,Grn,CA,T/S Black	HDSP-U511-MN000
HDSP-U513-KL000	S4,0.3UM,Grn,CC,T/S Black	HDSP-U513-MN000
HLMP-2300-EF000	L-Bar,.4inL X .195in W,HER	HLMP-2300-GH000
HLMP-2350-EF000	L-Bar,.8inL X .195inW,HER	HLMP-2350-GH000
HLMP-2500-FG000	L-Bar,.4inL X .195inW,Grn	HLMP-2500-GH000
HLMP-2550-FG000	L-Bar,.8inL X .195inW,Grn	HLMP-2550-GH000
HLMP-2620-EF000	L-Bar,.8inL X .4inW,HER,Quad	HLMP-2620-FG000
HLMP-2655-EF000	L-Bar,.4inL X .4inW,HER,Square	HLMP-2655-FG000
HLMP-2685-EF000	L-Bar,.8inL X .4inW,HER,Single	HLMP-2685-GH000
HLMP-2820-FG000	L-Bar,.8inL X .4inW,Grn,Quad	HLMP-2820-GH000
HLMP-2855-FG000	L-Bar,.4inL X .4inW,Grn,Square	HLMP-2855-GH000
HLMP-2870-FG000	L-Bar,.8inL X .4inW,Grn Dual	HLMP-2870-HI000
HLMP-2885-FG000	L-Bar,.8inL X .4inW,Grn,Single	HLMP-2885-HI000
HLMP-BD06-P0000	Lamp,5mm,AllnGaP2,Red,30X70deg	HLMP-BD07-P0000
HLMP-BD06-P00DD	Lamp,5mm,AllnGaP2,Red,30X70deg	HLMP-BD07-P00DD
HR5P-N150-00000	IR Lamp, 5mm, 850nm	HR5P-N1FB-00000
HR5P-N150-10000	IR Lamp, 5mm, 850nm	HR5P-N1FB-00000
HR5P-N3CA-00000	IR Lamp,5mm, 880nm,30deg	HR5P-N2CA-00000
HR5P-N3CB-00000	IR Lamp,5mm, 880nm,30deg	HR5P-N2CB-00000

Broadcom Part Numbers	Description	Suggested Replacement
HR5P-N3FA-00000	IR Lamp,5mm, 880nm,50deg	HR5P-N2FA-00000
HR5P-N3FB-00000	IR Lamp,5mm, 880nm,50deg	HR5P-N2FB-00000
HSMD-A100-K4PJ2	PLCC2,Top Mt,GaP,Org	HSMD-A100-L8PJ2
HSMG-A100-K42J2	PLCC2,Top Mt,GaP,Grn	HSMG-A100-K82J2
HZMS-A100-K20J2	PLCC2z,Top Mt,HER	HZMS-A100-L50J2
QDSP-S062	S4,Set of .56S AllnGaP DR CA/Overflow	NA
QDSP-U221-DE000	S4,0.3UM,HER,CA,T/S Black	QDSP-U221-GH000
QR5Z-N430-00000	IR Lamp, 5mm, 940nm	HR5P-N4CB-00000
QSMT-AW11-NUWZ1	MS AV,1W CWhite	NA
QSMT-AW13-NUWZ1	MS AV,1W CWhite	NA
QSMT-JW42-NWYJ1	MS JD,3W Mini CWhite	ASMT-JW32-NWY01
QSMT-JY42-NWXK1	MS JD,3W Mini WWhite	ASMT-JY32-NWY01

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Suggested Replacement
ASMF-LWG4-NQTAD	3030 0.5W White SMD-TLED	31 Jul 2023	31 Jan 2024	ASMF-LWG8-NRUAD
ASMF-LWG4-NRUFD	3030 0.5W White SMD-TLED	31 Jul 2023	31 Jan 2024	ASMF-LWG8-NTWFD
ASMF-LWG4-NRUGD	3030 0.5W White SMD-TLED	31 Jul 2023	31 Jan 2024	ASMF-LWG8-NTWGD
ASMF-LWG4-NRUHD	3030 0.5W White SMD-TLED	31 Jul 2023	31 Jan 2024	ASMF-LWG8-NTWHD
ASMF-LWG4-NRUJD	3030 0.5W White SMD-TLED	31 Jul 2023	31 Jan 2024	ASMF-LWG8-NSVJD
ASMT-AA00-ARS01	MS AV,1W Amber	31 Jul 2023	31 Jan 2024	ASMT-JA10-ARS01
ASMT-AG31-NUV00	MS AV,3W Green	31 Jul 2023	31 Jan 2024	ASM6-SGD1-NRT0H
ASMT-AH33-ATU00	MS AV,3W ROrg	31 Jul 2023	31 Jan 2024	NA
ASMT-AR00-AST01	MS AV,1W Red	31 Jul 2023	31 Jan 2024	ASMT-MR00-AHJ00
ASMT-MW04-NMN00	MS,1W,Cool White	31 Jul 2023	31 Jan 2024	ASMT-MW04-NLN00
ASMT-MW04-NMN01	MS,1W,Cool White	31 Jul 2023	31 Jan 2024	ASMT-JY32-NWY01
ASMT-MW04-NMNZ0	MS,1W,Cool White	31 Jul 2023	31 Jan 2024	ASMT-MW04-NLN01
ASMT-MWB4-NMN00	MS,1W,Cool White	31 Jul 2023	31 Jan 2024	NA
ASMT-MWB4-NMN01	MS,1W,Cool White	31 Jul 2023	31 Jan 2024	NA
ASMT-MY04-NNP00	MS,1W,Warm White	31 Jul 2023	31 Jan 2024	NA
ASMT-MYB4-NNP01	MS Diff,1W,Warm White	31 Jul 2023	31 Jan 2024	NA
ASMT-QWBG-NFHDE	PLCC4,MPWR,0.5W,InGaN,CWht,CRI80	31 Jul 2023	31 Jan 2024	NA
HCMS-2819	5X7 SmartDisp 8Char .15in,InGaN Blue	31 Jul 2023	31 Jan 2024	NA
HLMP-AB64-UVBZZ	Lamp,5mm,InGaN,Blue,30X70deg	31 Jul 2023	31 Jan 2024	HLMP-AB64-UVBDD
HLMP-AB65-TW0ZZ	Lamp,5mm,InGaN,Blue,30X70deg	31 Jul 2023	31 Jan 2024	HLMP-AB65-TW0DD
HLMP-AG64-X10ZZ	Lamp,5mm,AlInGaP,Red,30X70deg	31 Jul 2023	31 Jan 2024	HLMP-AG70-120DD
HLMP-AG66-120DD	Lamp,5mm,AlInGaP,Red,30X70deg	31 Jul 2023	31 Jan 2024	HLMP-AG70-120DD
HLMP-AG67-120DD	Lamp,5mm,AlInGaP,Red,30X70deg	31 Jul 2023	31 Jan 2024	HLMP-AG71-120DD
HLMP-CM3A-Z1B00	Lamp,5mm,InGaN,Grn,30deg	31 Jul 2023	31 Jan 2024	HLMP-CM3A-Z10DD
HLMP-CM3B-Z1BZZ	Lamp,5mm,InGaN,Grn,30deg	31 Jul 2023	31 Jan 2024	HLMP-CM3A-Z10DD
HLMP-CM3B-Z1CZZ	Lamp,5mm,InGaN,Grn,30deg	31 Jul 2023	31 Jan 2024	HLMP-CM3B-Z10DD
HLMP-ED3S-TV0DD	Lamp,5mm,AlInGaP,Red,30deg	31 Jul 2023	31 Jan 2024	HLMP-EG3G-VX0DD
HLMP-HL65-XYLDD	Lamp,5mm,AlInGaP,Amb,40X100deg	31 Jul 2023	31 Jan 2024	HLMP-HL65-XYKDD

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Suggested Replacement
HLMP-LG65-WX0DD	Lamp,4mm,AlInGaP,Red,50X100deg	31 Jul 2023	31 Jan 2024	HLMP-LG71-XZ0DD
HLMP-LM75-34NDD	Lamp,4mm,InGaN,Grn,40X100deg	31 Jul 2023	31 Jan 2024	HLMP-LM71-Z30DD
HLMP-LM75-34QDD	Lamp,4mm,InGaN,Grn,40X100deg	31 Jul 2023	31 Jan 2024	HLMP-LM71-Z30DD
HLMZ-CM3B-Z1BDD	LampZ,5mm,InGaN,Grn,30deg	31 Jul 2023	31 Jan 2024	NA
HLMZ-EG3B-WX0DD	LampZ,5mm,AlInGaP,Red,30deg	31 Jul 2023	31 Jan 2024	NA
HLMZ-HL65-XYKDD	LampZ,5mm,AlInGaP,Amb,40X100deg	31 Jul 2023	31 Jan 2024	NA
HLMZ-HL65-XYLDD	LampZ,5mm,AlInGaP,Amb,40X100deg	31 Jul 2023	31 Jan 2024	NA
HSMD-A100-L40J1	PLCC2,Top Mt,GaP,Org	31 Jul 2023	31 Jan 2024	HSMD-A100-N40J1
HSMG-A100-K72J2	PLCC2,Top Mt,GaP,Grn	31 Jul 2023	31 Jan 2024	HSMG-A100-K82J2
HSMG-A100-L82J1	PLCC2,Top Mt,GaP,Grn	31 Jul 2023	31 Jan 2024	HSMG-A100-M42J1
HZMD-A100-L40J1	PLCC2z,Top Mt,GaP,Org	31 Jul 2023	31 Jan 2024	HZMD-A100-N40J1
HZMG-A100-K72J2	PLCC2z,Top Mt,GaP,Grn	31 Jul 2023	31 Jan 2024	HSMG-A100-K82J2
HZMG-A100-L82J1	PLCC2z,Top Mt,GaP,Grn	31 Jul 2023	31 Jan 2024	HZMG-A100-M42J1
QLMP-HL78-XYKDD	Lamp,5mm,AlInGaP,Amb,40X100deg	31 Jul 2023	31 Jan 2024	NA
QLMZ-LG78-WX0DD	LampZ,4mm,AlInGaP,Red,50X100deg	31 Jul 2023	31 Jan 2024	NA
QSMS-C192	Chip,Top Mt,HER	31 Jul 2023	31 Jan 2024	HSMS-C191
QSMT-MW11-NLM01	MS,1W,Cool White	31 Jul 2023	31 Jan 2024	NA
QSMT-MW11-NMNJ1	MS,1W,Cool White	31 Jul 2023	31 Jan 2024	NA
QSMT-MW12-NLMJ1	MS,1W,Cool White	31 Jul 2023	31 Jan 2024	NA



Please provide your Broadcom Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy (LTB) order date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the Last Time Ship (LTS) date noted in the above table. Due to inherent variations in yields, Broadcom reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom's minimum order quantity (MOQ) requirements per the above table. All prior commitments regarding Broadcom's minimum order requirements do not apply to last time buy orders. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.