

# Product/Process Change Notice - PCN 18\_0006 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a change that will be made to certain ADI products (see Appendix A) that you may have purchased in the last 2 years. Any inquiries or requests with this PCN (additional data or samples) must be sent to ADI within 30 days of publication date. ADI contact information is listed below.

**PCN Title:** HMC941A Die Size Change

Publication Date: 02-Feb-2018

Effectivity Date: 31-May-2018 (the earliest date that a customer could expect to receive changed material)

	<b>D</b>
Ravision	Description:
1 10 1131011	Describilion.

П	1 :1: _	D-	lease
П	ınırıaı	120	

### **Description Of Change**

Die product HMC941A, will change to ~50um smaller on both width and length to match the HMC941 die product outline. There is no change in bond-pad locations.

## Reason For Change

The change in die dimensions is to make sure no assembly marginalities are experienced in the die-attach process when HMC941A device is used in lieu of HMC941 on the customers' existing substrates.

# Impact of the change (positive or negative) on fit, form, function & reliability

This change does not imply any change in device bond-wire assembly requirements, electrical specifications, device functionality and reliability.

Product Identification (this section will describe how to identify the changed material)

The die designator (die number) on the top metal layer is changed from ADHL3001 to ADHL3001A. Refer to the Supporting Documents section for details.

## **Summary of Supporting Information**

### Comments

Refer to attached supporting document for side by side comparison of the die drawings.

## **Supporting Documents**

Attachment 1: Type: Detailed Change Description

ADI\_PCN\_18\_0006\_Rev\_-\_HMC941A Detailed Change Description.pdf

For questions on this PCN, please send an email to the regional contacts below or contact your local ADI sales representatives.

Americas:PCN\_Americas@analog.comEurope:PCN\_Europe@analog.comJapan:PCN\_Japan@analog.comRest of Asia:PCN\_ROA@analog.com

Appendix A - Affected ADI Models				
Added Parts On This Revision - Product Family / Model Number (2)				
HMC941AG / HMC941A	HMC941AG/HMC941A-SX			

Appendix B - Revision History			
Rev	Publish Date	Effectivity Date	Rev Description
Rev	02-Feb-2018	31-May-2018	Initial Release.

Analog Devices, Inc.

Docld:4333 Parent Docld:None Layout Rev:7