

TE Connectivity

Product Change Notification: PCN-23-164725

PCN Date: 27-JAN-23

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

DEUTSCH DTM 2, 3 & 4 Position Plug and Receptacle Assembly Process Change

Description of Changes

The Industrial and Commercial Transportation business unit of TE Connectivity is making a change to the manufacturing process from manual to automated assembly machine for the part numbers listed below. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. Product drawing are not affected.

Reason for Changes:

Dear Customer, we hereby inform you of this change. The new assembly process is necessary to better meet our Customers demand needs. The change does not impact connector performance. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change is being phased in gradually and previous revisions revisions may be mixed.

PCN Attributes:					
Product Category:	Kind of Change:				
Connectors	Tooling-Process Change				
Change Feature:	Potential Customer Impact:				
No Feature Change	No Customer Impact				
Remarks:					

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Ship Date of Changed Items (Changed Parts Only):
	27-JAN-2023
Last Ship Date of Changed Items (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments
Effectivity Date:	Date of First Samples:

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
DTM04-2P	NO			"ZPF000000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			
DTM04-2P- E004	NO			"ZPF000000000130133", "DTM04-2P-E004- AS"			
DTM04-3P	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
<u>DTM04-3P-</u> <u>E004</u>	NO			"ZPF00000000130200"			
DTM04-4P	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
<u>DTM04-4P-</u> <u>E004</u>	NO			"ZPF00000000130265"			
DTM06-25	NO			"ZPF000000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
<u>DTM06-2S-</u> <u>E004</u>	NO			"ZPF000000000130142", "DTM06-2S-E004- AS"			
<u>DTM06-3S</u>	NO			"ZPF000000000130202", "DTM06-3S-LS", "DTM06-3S-L", "8202609699",			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"8202612555"			
DTM06-3S- E004	NO			"ZPF000000000130203", "DTM06-3S-E004- AS"			
DTM06-45	NO			"ZPF000000000130267", "8202606979"			
<u>DTM06-4S-</u> <u>E004</u>	NO			"ZPF00000000130268"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>DTM04-2P-</u> <u>E004</u>	NO			"ZPF000000000130133", "DTM04- 2P-E004-AS"			
<u>DTM04-3P-</u> <u>E004</u>	NO			"ZPF000000000130200"			
<u>DTM06-2S-</u> <u>E004</u>	NO			"ZPF000000000130142", "DTM06- 2S-E004-AS"			
<u>DTM06-3S-</u> E004	NO			"ZPF000000000130203", "DTM06- 3S-E004-AS"			
<u>DTM06-4S</u>	NO			"ZPF000000000130267", "8202606979"			
<u>DTM06-4S-</u> <u>E004</u>	NO			"ZPF000000000130268"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>DTM04-2P-</u> <u>E004</u>	NO			"ZPF000000000130133", "DTM04- 2P-E004-AS"			
<u>DTM04-3P-</u> <u>E004</u>	NO			"ZPF000000000130200"			
<u>DTM06-2S-</u> <u>E004</u>	NO			"ZPF000000000130142", "DTM06- 2S-E004-AS"			
<u>DTM06-3S-</u> <u>E004</u>	NO			"ZPF000000000130203", "DTM06- 3S-E004-AS"			
DTM06-4S	NO			"ZPF000000000130267", "8202606979"			
DTM06-4S- E004	NO			"ZPF00000000130268"			

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number		Number	Part Number(s)	Difference
<u>DTM04-</u> <u>3P</u>	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<u>DTM04-2P</u>	NO			"ZPF000000000130131", "DTM04-2P-AS", "DTM04-2P-LS", "DTM04-2P-L"			
<u>DTM04-</u> 2P-E004	NO			"ZPF000000000130133", "DTM04-2P-E004- AS"			
DTM04-3P	NO			"ZPF000000000130198", "DTM04-3P-LD", "DTM04-3P-LS", "DTM04-3P-L"			
DTM04- 3P-E004	NO			"ZPF00000000130200"			
DTM04-4P	NO			"ZPF000000000130263", "DTM04-4P-LS", "DTM04-4P-L", "8202609556", "MSE04832"			
<u>DTM04-</u> 4P-E004	NO			"ZPF00000000130265"			
DTM06-25	NO			"ZPF000000000130139", "DTM06-2S-LS", "DTM06-2S-L", "8202609944"			
<u>DTM06-</u> 2S-E004	NO			"ZPF000000000130142", "DTM06-2S-E004- AS"			
DTM06-35	NO			"ZPF000000000130202", "DTM06-3S-LS", "DTM06-3S-L", "8202609699", "8202612555"			
DTM06-4S	NO			"ZPF000000000130267", "8202606979"			